

Richard Guerzon (843) 303-7671 115 Piedmont Street Duncan, South Carolina 29334	Year: 2013 Make: Toyota Model: Venza Color: White	VIN: 4T3ZA3BB5DU081065 License: 1120PM Odometer: 149,263	Customer Arrival Time 08-07-2025 04:05 PM Service Completed Time 08-07-2025 05:31 PM
--	--	---	---

Service Description	Quantity	Price
Walmart.com	4	PREPAID
Rotation + lifetime balance	4	PREPAID
Road hazard protection warranty	4	PREPAID
TPMS	4	PREPAID
Service Total (Excluding Tax & Govt. Fees):		\$0.00

Merchandise Description	Quantity	Price
Green Max Optimum Sport HP Performance 245/55R19 103V Passenger Tire	1	PREPAID
Green Max Optimum Sport HP Performance 245/55R19 103V Passenger Tire	1	PREPAID
Green Max Optimum Sport HP Performance 245/55R19 103V Passenger Tire	1	PREPAID
Green Max Optimum Sport HP Performance 245/55R19 103V Passenger Tire	1	PREPAID
Merchandise Total (Excluding Tax):		\$0.00
Total (Excluding Tax & Govt. Fees):		\$0.00

Vehicle Checks & Services Performed					
Balance tires	COMPLETE-Drv rear	Lugnut torque	76-Drv front, 76	TPMS Relearn	NON-APPLICABLE-Pass front
Balance tires	COMPLETE-Drv front	Lugnut torque	76-Pass front, 76	TPMS Relearn	NON-APPLICABLE-Pass rear
Balance tires	COMPLETE-Pass front	Lugnut torque	76-Pass rear, 76	Mount Tires	COMPLETE-Drv rear
Balance tires	COMPLETE-Pass rear	Scan existing DOTs	Not Performed-Drv rear	Mount Tires	COMPLETE-Drv front
Scan new DOTs	COMPLETE-Drv rear, 05HC2L0394224	Scan existing DOTs	Not Performed-Drv front	Mount Tires	COMPLETE-Pass front
Scan new DOTs	COMPLETE-Drv front, 05HC2L0390625	Scan existing DOTs	Not Performed-Pass front	Mount Tires	COMPLETE-Pass rear
Scan new DOTs	COMPLETE-Pass front, 05HC2L0390625	Scan existing DOTs	Not Performed-Pass rear	Dispose of old tires	COMPLETE-Drv rear
Scan new DOTs	COMPLETE-Pass rear, 05HC2L0390625	Tire pressure check	CHECKED-Drv rear, 32 PSI	Dispose of old tires	COMPLETE-Drv front
Install TPMS Service Pack	COMPLETE-Drv rear	Tire pressure check	CHECKED-Drv front, 32 PSI	Dispose of old tires	COMPLETE-Pass front
Install TPMS Service Pack	COMPLETE-Drv front	Tire pressure check	CHECKED-Pass front, 32 PSI	Dispose of old tires	COMPLETE-Pass rear
Install TPMS Service Pack	COMPLETE-Pass front	Tire pressure check	CHECKED-Pass rear, 32 PSI	Check Battery	NON-APPLICABLE
Install TPMS Service Pack	COMPLETE-Pass rear	TPMS Relearn	NON-APPLICABLE-Drv rear		
Lugnut torque	76-Drv rear, 76	TPMS Relearn	NON-APPLICABLE-Drv front		

Damages Noted Before Service	Type of Damage	Additional Comments
None	--	--

Battery Test Results
Result: DECLINED (NON-APPLICABLE)

Technician Names	Customer Comments	Technician Comments
Service Writer/Greeter: Joshua P.	No locking lugnuts	TPMs flashing pts
Tire tech: Joshua P.	Customer opted in for road hazard.	Installing new sensors can't be programmed
Tire tech: Bryson L.	Lift on 3 tq 76	
Tire tech: Joshua P.		
Battery tech: Joshua P.		

Customer Service Agreement

authorize the stated service to be completed with the necessary materials. I give permission to operate the vehicle.

understand:

Customer Signature:

Date: 08-07-2025

1. Walmart does not inspect tires to determine if they are safe or have been recalled. Tires are not examined for conditions that may affect safety (tread depth, cuts, punctures, cracking, bulges, or uneven tread wear).

2. Only the service(s) listed on the service order are performed.

3. During oil changes, Walmart only checks and adjusts tire air pressure.

4. Walmart does not check tire age or air pressure of the spare tire.

5. Customers should regularly confirm that their tires, including any spare, are properly inflated, have tread depth greater than 2/32" in all grooves, and have no cuts, punctures, cracking, bulges, or uneven tread wear.

6. Driving conditions will affect tire performance.

Customer Notification and Disclaimer
Walmart may conduct complimentary courtesy checks based on your selection of service packages. Courtesy checks vary by service package and could include the following: checking of tire pressure, light bulb testing, fluid refills (washer, transmission, and power steering), battery check, interior vacuuming and checking of the wiper blades.
NOTICE: Manufacturer Special Policy Adjustment Programs Federal law requires manufacturers to furnish the National Highway Traffic Safety Administration (N.H.T.S.A.) with bulletins describing any defects in their vehicles. You may obtain copies of these bulletins either from the manufacturer or N.H.T.S.A. In addition, certain consumer publications or organizations publish this information, which may be available for a fee or for free.